


EPA Region 5 Records Ctr.



345417

APPENDIX
PHOTOGRAPHIC LOG
(21 Pages)



Tetra Tech EM Inc.



Photograph No.: 1
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Mobilization to the site

Orientation: West
Date: 24 Oct 01



Photograph No.: 2
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Building #1 car crusher pit - Lefton West Site

Orientation: West
Date: 14 Nov 01



Tetra Tech EM Inc.



Photograph No.: 3

Orientation: North

TDD Number: S05-0109-011

Date: 14 Nov 01

Location: Lefton Iron & Metal Removal

Subject: Contractor scrap steel loading area at the Lefton West Site



Photograph No.: 4

Orientation: Southeast

TDD Number: S05-0109-011

Date: 27 Nov 01

Location: Lefton Iron & Metal Removal

Subject: Scrap steel stockpile adjacent to the contractor sorting area



Tetra Tech EM Inc.



Photograph No.: 5

TDD Number: S05-0109-011

Location: Lefton Iron & Metal Removal

Subject: Auto-fluff and soil matrix near building #2

Orientation: South

Date: 07 Dec 01



Photograph No.: 6

TDD Number: S05-0109-011

Location: Lefton Iron & Metal Removal

Subject: Soil stockpile from cells G-5 and G-6

Orientation: Southwest

Date: 07 Dec 01



Tetra Tech EM Inc.



Photograph No.: 7
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Trash and scrap steel located at the mid-part of the Lefton East Site

Orientation: West
Date: 10 Dec 01



Photograph No.: 8
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: USAF EOD personnel places explosive charges on practice (dummy) bombs

Orientation: South
Date: 11 Dec 01



Tetra Tech EM Inc.



Photograph No.: 9

Orientation: West

TDD Number: S05-0109-011

Date: 28 Dec 01

Location: Lefton Iron & Metal Removal

Subject: Furnace containing N.O.R.M. firebrick is off-loaded



Photograph No.: 10

Orientation: East

TDD Number: S05-0109-011

Date: 01 Feb 02

Location: Lefton Iron & Metal Removal

Subject: Loading used RR ties for disposal from the Lefton East Site




Tetra Tech EM Inc.



Photograph No.: 11
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Construction of East Site haul road, loading pad and upgrade to RR siding

Orientation: East
Date: 18 Feb 02



Photograph No.: 12
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Every third or damaged RR tie is replaced to bring siding up to specification

Orientation: North
Date: 21 Feb 02



Tetra Tech EM Inc.



Photograph No.: 13
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Loading PCB impacted soil for delivery to the Lefton East Site rail loading spur

Orientation: West
Date: 28 Feb 02



Photograph No.: 14
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Scrap tire loading for off-site recycling by the Illinois EPA Tire Program

Orientation: North
Date: 28 Feb 02



Tetra Tech EM Inc.



Photograph No.: 15

Orientation: West

TDD Number: S05-0109-011

Date: 28 Feb 02

Location: Lefton Iron & Metal Removal

Subject: Progress of PCB impacted soil removal and loading at the Lefton West Site



Photograph No.: 16

Orientation: Southwest

TDD Number: S05-0109-011

Date: 28 Feb 02

Location: Lefton Iron & Metal Removal

Subject: Same as previous



Tetra Tech EM Inc.



Photograph No.: 17
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Progress of PCB impacted soil removal and loading at the Lefton West Site
Orientation: South
Date: 28 Feb 02



Photograph No.: 18
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Same as previous
Orientation: Southeast
Date: 28 Feb 02



Tetra Tech EM Inc.



Photograph No.: 19

Orientation: East

TDD Number: S05-0109-011

Date: 28 Feb 02

Location: Lefton Iron & Metal Removal

Subject: Stockpile of PCB impacted soil awaiting loading into railcars



Photograph No.: 20

Orientation: North

TDD Number: S05-0109-011

Date: 28 Feb 02

Location: Lefton Iron & Metal Removal

Subject: Railcar is covered prior to transportation to the TSCA landfill in Oklahoma



Tetra Tech EM Inc.



Photograph No.: 21

Orientation: West

TDD Number: S05-0109-011

Date: 12 Mar 02

Location: Lefton Iron & Metal Removal

Subject: Two 20,000 gallon diesel tanks are emptied, cleaned and removed from service



Photograph No.: 22

Orientation: Southeast

TDD Number: S05-0109-011

Date: 13 Mar 02

Location: Lefton Iron & Metal Removal

Subject: Local utility company prepares to remove PCB transformer for no charge



Tetra Tech EM Inc.



Photograph No.: 23

Orientation: West

TDD Number: S05-0109-011

Date: 14 Mar 02

Location: Lefton Iron & Metal Removal

Subject: Diesel tanks are removed after cleaning operation



Photograph No.: 24

Orientation: North

TDD Number: S05-0109-011

Date: 14 Mar 02

Location: Lefton Iron & Metal Removal

Subject: Diesel impacted soil is removed



Tetra Tech EM Inc.



Photograph No.: 25

Orientation: North

TDD Number: S05-0109-011

Date: 23 Apr 02

Location: Lefton Iron & Metal Removal

Subject: Drum carcasses discovered at both the surface and below surface



Photograph No.: 26

Orientation:

TDD Number: S05-0109-011

Date: 26 Apr 02

Location: Lefton Iron & Metal Removal

Subject: Drums for removal from Pit #2 next to former car crusher building



Tetra Tech EM Inc.



Photograph No.: 27
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Stockpile next to rail loading spur

Orientation: South
Date: 23 May 02



Photograph No.: 28
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Buried tires are removed from the Lefton East Site

Orientation: West
Date: 23 May 02



Tetra Tech EM Inc.



Photograph No.: 29

Orientation: West

TDD Number: S05-0109-011

Date: 04 Jun 02

Location: Lefton Iron & Metal Removal

Subject: Orange snow fence is placed according to grid network locations that contain remnant PCB impacted soil above 50 ppm at the West facility



Photograph No.: 30

Orientation: Southwest

TDD Number: S05-0109-011

Date: 04 Jun 02

Location: Lefton Iron & Metal Removal

Subject: Same as photo # 29



Tetra Tech EM Inc.



Photograph No.: 31

Orientation: South

TDD Number: S05-0109-011

Date: 05 Jun 02

Location: Lefton Iron & Metal Removal

Subject: Scrap tires are cleaned of soil prior to pick-up by the IEPA tire disposal program



Photograph No.: 32

Orientation: South

TDD Number: S05-0109-011

Date: 07 Jun 02

Location: Lefton Iron & Metal Removal

Subject: Clean backfill is delivered, placed and machine compacted in-place



Tetra Tech EM Inc.



Photograph No.: 33
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Same as Photo # 32

Orientation: Southwest
Date: 07 Jun 02



Photograph No.: 34
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Remaining vegetation is chipped and used as erosion control

Orientation: South
Date: 20 Aug 02



Tetra Tech EM Inc.



Photograph No.: 35

Orientation: East

TDD Number: S05-0109-011

Date: 12 Sep 02

Location: Lefton Iron & Metal Removal

Subject: Drought resistant grass seed starts to germinate (Demobilization - East Facility)



Photograph No.: 36

Orientation: North

TDD Number: S05-0109-011

Date: 12 Sep 02

Location: Lefton Iron & Metal Removal

Subject: Access to the East facility is blocked to restrict site access (Demobilization)



Tetra Tech EM Inc.



Photograph No.: 37

Orientation: North

TDD Number: S05-0109-011

Date: 12 Sep 02

Location: Lefton Iron & Metal Removal

Subject: Site restoration complete (Demobilization)



Photograph No.: 38

Orientation: Northwest

TDD Number: S05-0109-011

Date: 12 Sep 02

Location: Lefton Iron & Metal Removal

Subject: Demobilization



Tetra Tech EM Inc.



Photograph No.: 39
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Demobilization

Orientation: West
Date: 12 Sep 02



Photograph No.: 40
TDD Number: S05-0109-011
Location: Lefton Iron & Metal Removal
Subject: Site restoration complete (Demobilization)

Orientation: Southwest
Date: 12 Sep 02



Tetra Tech EM Inc.



Photograph No.: 41

Orientation: South

TDD Number: S05-0109-011

Date: 12 Sep 02

Location: Lefton Iron & Metal Removal

Subject: Site restoration complete (Demobilization)



Photograph No.: 42

Orientation: Southeast

TDD Number: S05-0109-011

Date: 12 Sep 02

Location: Lefton Iron & Metal Removal

Subject: Site restoration complete (Demobilization)